



SWIFTPPOINT

Quick Start Guide



TRACPOINT


TRACPOINT Features



Charging the TRACPOINT

To charge your TRACPOINT mouse:

1. Plug the USB charger into a USB port on your computer or into a USB charging accessory.
2. Place the mouse onto the Charger.



The battery LED will flash green while charging and turns off once fully charged. The first 60 seconds of charging will give up to one hour of use. A full charge can take up to 90 minutes, giving up to 2 weeks of use. To begin using the mouse, move the switch on the underside to the **ON** position

When not using the mouse for brief periods, dock the mouse on the USB charger so it maintains a charge.

The mouse should be fully charged periodically.

When not using the mouse for extended periods, move the switch on the underside of the mouse to **OFF**.

Connecting the TRACPOINT via Bluetooth 4.0

Once the mouse is charged, you can pair it to your computer via Bluetooth 4.0.

Leave the mouse **OFF** for the first three steps.

1. Go to Bluetooth device menu in your system settings
 - Windows: Settings > Devices > Add Bluetooth device
 - MacOS: System Preferences/Settings > Bluetooth
2. Ensure Bluetooth is switched on, on your device.
3. Remove any existing “TRACPOINT” entries in the list by selecting it, then select **Remove**
4. While holding down the front button on the mouse, move the switch on the underside of the mouse to **ON**. Then release the front button as soon as the LED starts to flash orange.

Note: If you hold the front button for more than 5 seconds, the mouse will change out of Bluetooth pairing mode, flash green and not initiate a Bluetooth pairing process.

5. When “TRACPOINT” appears in the list of searched devices, click on the it to pair your mouse.
6. If you have a problem, switch the mouse Off then On, and try again from step 1.

If “TRACPOINT ” does not appear, make sure your system supports Bluetooth 4 and Bluetooth is switched on.

Please note that Windows 7 does not support Bluetooth 4.0, however you can purchase a USB Receiver which will work on Windows 7. Accessories can be purchased from the Swiftpoint Webpage, www.swiftpoint.com, and at other approved outlets.

Connecting to more than one Bluetooth device

- TRACPOINT can store pairings with up to 3 Bluetooth devices.
- When switched on, the mouse will first try to reconnect with the most recently used device. If this cannot be found it will try to connect to the next device in the list.
- If two or more of the TRACPOINT's current Bluetooth connections are available nearby, you can swap between them by holding the rear button while switching **OFF** then **ON** again using the On/Off switch.

Configuring TRACPOINT on PC and Mac

IMPORTANT

Install the SWIFTPPOINT CONTROL PANEL to configure the TRACPOINT mouse to perform exactly as you want it to. Set the cursor speed, the scroll speed and direction, assign button functionality and much more.


The driver will be updated periodically to give even more functions later on, to make the TRACPOINT the best mousing experience you can have.

1. Open browser, click in URL box and type:
www.swiftpoint.com/download-tracpoint-driver
2. Follow the on-line instructions

Using the TRACPOINT

Hold the mouse with your thumb on the thumb grip and your middle finger on the finger grip. Rest your index finger on the front button.

- To right-click, move your index finger to the rear button
- Use your index finger to roll the scroll wheel



Tilt + Move Gestures Functions

To perform tilt gestures:


Tilt the mouse to the right to engage the tilt gestures and move the mouse sideways, backwards, or forwards.



- Move mouse forward - Scroll down
- Move mouse backward - Scroll up
- Swipe mouse left - Left pan
- Swipe mouse right - Right pan

The directions may differ depending on the application and system setup.

Tilt Rear Button Gesture Functions




All tilt gestures can be reassigned using the CONTROL PANEL and assign different functions.

Presentation Mode

Presentation mode operates with Microsoft PowerPoint and some other presentation applications.


Open your presentation and start the show.

Move the switch on the underside of the mouse to **PRESENT**



Presentation Mode - Functions

Hold the mouse in the palm of your hand and use your thumb to operate.



- Advance Slides/Left Click - Tap front buttons
- Move cursor - Press and hold front button
- Previous Slide - Tap rear button
- Virtual Laser Pointer - Press and hold rear button
- Application switcher - Press and hold rear then front buttons

Move the switch on the underside of the mouse to **ON** to return to standard mouse functionality.

For more tips and videos for TRACPOINT, visit

www.swiftpoint.com/tracpoint-support

Specifications

Operating Systems

- Windows 8 & 10 or higher
- MacOS 10.4 or higher
- Android 4.4 or higher

Communications

- Bluetooth 4.0
- USB Wireless (2.4GHz), for Windows 7 PCs (with USB Charger/Receiver purchased separately)

Power

- Li-Ion Battery 3.7V, 120mAh
- Charging: USB Outlet, 5V \square , 130mA

Install the **SWIFTPPOINT CONTROL PANEL** at www.swiftpoint.com/download-tracpoint-drivers